









TE 6-A36

English
עברית


1
15




2**3****4****5**




10



11



12



13



TE 6-A36

| | | |
|----|---------------------------------------|----|
| en | Original operating instructions | 1 |
| he | הוראות הפעלה מקוריות | 15 |

Original operating instructions

1 Information about the operating instructions

1.1 About these operating instructions

- Read these operating instructions before the product is used or operated for the first time. This is a prerequisite for safe, trouble-free handling and use of the product.
- Observe the safety instructions and warnings in these operating instructions and on the product.
- Always keep the operating instructions with the product and make sure that the product is accompanied by these operating instructions only, when the product is given to other persons.

1.2 Explanation of symbols

1.2.1 Warnings

Warnings alert persons to hazards that occur when handling or using the product. The following signal words are used:



DANGER !

- ▶ Draws attention to imminent danger that will lead to serious personal injury or fatality.



WARNING !

- ▶ Draws attention to a potential threat of danger that can lead to serious injury or fatality.



CAUTION !

- ▶ Draws attention to a potentially dangerous situation that could lead to personal injury or damage to the equipment or other property.

1.2.2 Symbols in the operating instructions

The following symbols are used in these operating instructions:

| | |
|--|---|
| | Comply with the operating instructions |
| | Instructions for use and other useful information |
| | Dealing with recyclable materials |
| | Do not dispose of electric equipment and batteries as household waste |
| | Hilti Li-ion battery |
| | Hilti charger |

1.2.3 Symbols in illustrations

The following symbols are used in illustrations:

| | |
|-----------|--|
| 2 | These numbers refer to the illustrations at the beginning of these operating instructions. |
| 3 | The numbers in illustrations refer to important work steps or to components important for the work steps. In the text, the corresponding numbers draw attention to these work steps or components, e.g. (3) . |
| 11 | Item reference numbers are used in the overview illustration and refer to the numbers used in the key in the product overview section. |
| ! | This symbol is intended to draw your special attention to certain points for handling the product. |



1.3 Product-dependent symbols

1.3.1 Symbols on the product

The following symbols can be used on the product:

| | |
|--|--|
| | Drilling without hammer action |
| | Drilling with hammer action (hammer drilling) |
| | Chiseling |
| | Chisel positioning |
| | Forward / reverse |
| | Rated speed under no load |
| | Direct current (DC) |
| | The product supports wireless data transmission compatible with iOS and Android platforms. |
| | Hilti Li-ion battery type series used. Observe the information given in the section headed Intended use . |
| | Li-ion battery |
| | Never use the battery as a striking tool. |
| | Do not drop the battery. Never use a battery that has suffered an impact or is damaged in any other way. |

1.4 Product information

Hilti products are designed for professional use and may be operated, serviced and maintained only by trained, authorized personnel. This personnel must be specifically informed about the possible hazards. The product and its ancillary equipment can present hazards if used incorrectly by untrained personnel or if used not in accordance with the intended use.

The type designation and serial number are printed on the rating plate.

- Write down the serial number in the table below. You will be required to state the product details when contacting Hilti Service or your local Hilti organization to inquire about the product.

Product information

| | |
|---------------|----------|
| Rotary hammer | TE 6-A36 |
| Generation: | 04 |
| Serial no.: | |

1.5 Declaration of conformity

We declare, on our sole responsibility, that the product described here complies with the applicable directives and standards. A copy of the declaration of conformity can be found at the end of this documentation.

The technical documentation is filed here:

Hilti Entwicklungsgesellschaft mbH | Tool Certification | Hiltistrasse 6 | 86916 Kaufering, Germany

2 Safety

2.1 General power tool safety warnings

⚠ WARNING Read all safety warnings, instructions, illustrations and specifications provided with this power tool. Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury. Save all warnings and instructions for future reference.

The term "power tool" in the warnings refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.



Work area safety

- ▶ **Keep work area clean and well lit.** Cluttered or dark areas invite accidents.
- ▶ **Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.** Power tools create sparks which may ignite the dust or fumes.
- ▶ **Keep children and bystanders away while operating a power tool.** Distractions can cause you to lose control.

Electrical safety

- ▶ **Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools.** Unmodified plugs and matching outlets will reduce risk of electric shock.
- ▶ **Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators.** There is an increased risk of electric shock if your body is earthed or grounded.
- ▶ **Do not expose power tools to rain or wet conditions.** Water entering a power tool will increase the risk of electric shock.
- ▶ **Do not abuse the cord.** Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts. Damaged or entangled cords increase the risk of electric shock.
- ▶ **When operating a power tool outdoors, use an extension cord suitable for outdoor use.** Use of a cord suitable for outdoor use reduces the risk of electric shock.
- ▶ **If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply.** Use of an RCD reduces the risk of electric shock.

Personal safety

- ▶ **Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication.** A moment of inattention while operating power tools may result in serious personal injury.
- ▶ **Use personal protective equipment. Always wear eye protection.** Protective equipment such as a dust mask, non-skid safety shoes, hard hat or hearing protection used for appropriate conditions will reduce personal injuries.
- ▶ **Prevent unintentional starting.** Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool. Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
- ▶ **Remove any adjusting key or wrench before turning the power tool on.** A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- ▶ **Do not overreach.** Keep proper footing and balance at all times. This enables better control of the power tool in unexpected situations.
- ▶ **Dress properly.** Do not wear loose clothing or jewellery. Keep your hair and clothing away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- ▶ **If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used.** Use of dust collection can reduce dust-related hazards.
- ▶ **Do not let familiarity gained from frequent use of tools allow you to become complacent and ignore tool safety principles.** A careless action can cause severe injury within a fraction of a second.

Power tool use and care

- ▶ **Do not force the power tool.** Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- ▶ **Do not use the power tool if the switch does not turn it on and off.** Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- ▶ **Disconnect the plug from the power source and/or remove the battery pack, if detachable, from the power tool before making any adjustments, changing accessories, or storing power tools.** Such preventive safety measures reduce the risk of starting the power tool accidentally.
- ▶ **Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool.** Power tools are dangerous in the hands of untrained users.
- ▶ **Maintain power tools and accessories.** Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- ▶ **Keep cutting tools sharp and clean.** Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.



- ▶ Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be performed. Use of the power tool for operations different from those intended could result in a hazardous situation.
- ▶ **Keep handles and grasping surfaces dry, clean and free from oil and grease.** Slippery handles and grasping surfaces do not allow for safe handling and control of the tool in unexpected situations.

Battery tool use and care

- ▶ **Recharge only with the charger specified by the manufacturer.** A charger that is suitable for one type of battery pack may create a risk of fire when used with another battery pack.
- ▶ **Use power tools only with specifically designated battery packs.** Use of any other battery packs may create a risk of injury and fire.
- ▶ **When battery pack is not in use, keep it away from other metal objects, like paper clips, coins, keys, nails, screws or other small metal objects, that can make a connection from one terminal to another.** Shorting the battery terminals together may cause burns or a fire.
- ▶ **Under abusive conditions, liquid may be ejected from the battery; avoid contact.** If contact accidentally occurs, flush with water. If liquid contacts eyes, additionally seek medical help. Liquid ejected from the battery may cause irritation or burns.
- ▶ **Do not use a battery pack or tool that is damaged or modified.** Damaged or modified batteries may exhibit unpredictable behaviour resulting in fire, explosion or risk of injury.
- ▶ **Do not expose a battery pack or tool to fire or excessive temperature.** Exposure to fire or temperature above 130° C (265 °F) may cause explosion.
- ▶ **Follow all charging instructions and do not charge the battery pack or tool outside the temperature range specified in the instructions.** Charging improperly or at temperatures outside the specified range may damage the battery and increase the risk of fire.

Service

- ▶ **Have your power tool serviced by a qualified repair person using only identical replacement parts.** This will ensure that the safety of the power tool is maintained.
- ▶ **Never service damaged battery packs.** Service of battery packs should only be performed by the manufacturer or authorized service providers.

2.2 Hammer safety warnings

Safety instructions for all operations

- ▶ **Wear ear protectors.** Exposure to noise can cause hearing loss.
- ▶ **Use auxiliary handle(s), if supplied with the tool.** Loss of control can cause personal injury.
- ▶ **Hold the power tool by insulated gripping surfaces, when performing an operation where the cutting accessory may contact hidden wiring.** Cutting accessory contacting a "live" wire may make exposed metal parts of the power tool "live" and could give the operator an electric shock.

Safety instructions when using long drill bits with rotary hammers

- ▶ **Always start drilling at low speed and with the bit tip in contact with the workpiece.** At higher speeds, the bit is likely to bend if allowed to rotate freely without contacting the workpiece, resulting in personal injury.
- ▶ **Apply pressure only in direct line with the bit and do not apply excessive pressure.** Bits can bend causing breakage or loss of control, resulting in personal injury.

2.3 Additional safety instructions for rotary hammer drill

Personal safety

- ▶ Use the product and accessories only when they are in perfect working order.
- ▶ Never tamper with or modify the product or accessories in any way.
- ▶ Use auxiliary handles supplied with the product. Loss of control can cause personal injury.
- ▶ Apply appropriate safety measures at the opposite side of the workpiece in work that involves breaking through. Parts breaking away could fall out and / or fall down causing injury to other persons.
- ▶ Always hold the tool with both hands on the grips provided. Keep the grips clean and dry.
- ▶ Hold the product by the insulated gripping surfaces when performing work in which the accessory tool might come into contact with concealed wiring. If the accessory tool comes into contact with a live wire, metal parts of the power tool can also become live, resulting in an electric shock.
- ▶ Do not touch rotating parts – risk of injury!
- ▶ Wear eye protection, a hard hat and ear protection and suitable respiratory protection while the product is in use.



- ▶ Wear protective gloves when changing the accessory tool. Touching the accessory tool can result in cuts and burns.
- ▶ Wear eye protection. Flying fragments can injure the body and eyes.
- ▶ Dust produced by grinding, sanding, cutting and drilling can contain dangerous chemicals. Some examples are: lead or lead-based paints; brick, concrete and other masonry products, natural stone and other products containing silicates; certain types of wood, such as oak, beech and chemically treated wood; asbestos or materials that contain asbestos. Determine the exposure of the operator and bystanders by means of the hazard classification of the materials to be worked. Implement the necessary measures to restrict exposure to a safe level, for example by the use of a dust collection system or by the wearing of suitable respiratory protection. The general measures for reducing exposure include:
 - ▶ working in an area that is well ventilated,
 - ▶ avoidance of prolonged contact with dust,
 - ▶ directing dust away from the face and body,
 - ▶ wearing protective clothing and washing exposed areas of the skin with water and soap.
- ▶ Take frequent breaks and do physical exercises to improve the blood circulation in your fingers. High vibration during long periods of work can lead to disorders of the blood vessels and nervous system in the fingers, hands and wrists.

Electrical safety

- ▶ Before beginning work, check the working area for concealed electric cables or gas and water pipes. External metal parts of the product could give you an electric shock or cause an explosion if you accidentally damage an electric cable or a gas or water pipe.

Power tool use and care

- ▶ Switch the product off immediately if the accessory tool jams. The product might twist off-line.
- ▶ Wait until the product has come to a complete stop before you lay it down.

2.4 Safety instructions

- ▶ Observe all safety instructions in this documentation and on the device.
- ▶ Use respiratory protection to keep residual dust away from the face and airways when drilling and when servicing the tool or accessories.
- ▶ Always use the side handle on the **Hilti** rotary hammer drill, even when the dust removal module is fitted.


2.5 Careful handling and use of batteries

- ▶ Observe the special guidelines applicable to the transport, storage and use of lithium-ion batteries.
- ▶ Do not expose batteries to high temperatures, direct sunlight or fire.
- ▶ Do not disassemble, crush or incinerate batteries and do not subject them to temperatures over 80 °C (176 °F).
- ▶ Do not use or charge batteries that have suffered mechanical impact, have been dropped from a height or show signs of damage. In this case, always contact your **Hilti Service**.
- ▶ If the battery is too hot to touch it may be defective. Put the battery in a place where it is clearly visible and where there is no risk of fire, at an adequate distance from flammable materials. Allow the battery to cool down. If it is still too hot to touch after an hour, the battery is faulty. Contact **Hilti Service**.



3 Description

3.1 Product overview 1



- (1) Dust shield
- (2) tool holder
- (3) Insert tool unlocking device
- (4) Depth gauge
- (5) Function selector switch
- (6) Forward / reverse switch with switch-on interlock
- (7) Control switch
- (8) Grip
- (9) Battery release buttons
- (10) Charge status and fault display (Li-ion battery)
- (11) Battery
- (12) Connection for the TE DRS-6-A(02) dust removal module
- (13) Side handle
- (14) Light to illuminate the work area

3.2 Intended use

The product described is a cordless rotary hammer drill. It is designed for drilling in steel, wood and masonry, for hammer-action drilling in concrete and masonry, and for driving and removing screws. The product can also be used for light chiseling work on masonry and surface finishing on concrete.

- Use only Hilti Li-ion batteries from the B 36 series with this product.
- Use only the Hilti battery chargers from the C4/36 series for these batteries.

3.3 Lithium-ion battery status display

The charge status of the Li-ion battery and malfunctions of the power tool are indicated by the display on the Li-ion battery. The charge status of the Li-ion battery is displayed after pressing one of the two battery release buttons.

| Status | Meaning |
|------------------|------------------------------|
| 4 LEDs light up. | Charge status: 75 % to 100 % |
| 3 LEDs light up. | Charge status: 50 % to 75 % |
| 2 LEDs light up. | Charge status: 25 % to 50 % |
| 1 LED lights up. | Charge status: 10 % to 25 % |
| 1 LED blinks. | Charge status: < 10 % |

i Battery charge status cannot be displayed while the control switch is pressed and for up to 5 seconds after releasing the control switch. If the battery display LEDs blink, please observe the instructions given in the Troubleshooting section.

3.4 Items supplied

Rotary hammer, side handle, depth gauge, operating instructions.

Other system products approved for use with this product can be found at your local **Hilti Store** or at: www.hilti.group

4 Technical data

4.1 Battery

| | |
|-----------------------------------|------------------|
| Battery operating voltage | 36 V |
| Ambient temperature for operation | -17 °C ... 60 °C |



| | |
|--|------------------|
| Storage temperature | -20 °C ... 40 °C |
| Battery charging starting temperature | -10 °C ... 45 °C |

4.2 Rotary hammer

| | |
|---|-----------------|
| | TE 6-A36 |
| Rated voltage | 36 V |
| Weight in accordance with EPTA procedure 01/2003 | 3.7 kg |
| Rated speed under no load | 1,050 /min |
| Single impact energy in accordance with EPTA procedure 05/2009 | 2.5 J |
| Drilling diameter range in concrete/masonry (hammer drilling) | 4 mm ... 28 mm |
| Drilling diameter range in wood (solid) | 3 mm ... 20 mm |
| Drilling diameter range in metal (solid-head drill bit) | 3 mm ... 13 mm |

4.3 Noise information and vibration values in accordance with EN 62841

The sound pressure and vibration values given in these instructions were measured in accordance with a standardized test and can be used to compare one power tool with another. They can also be used for a preliminary assessment of exposure.

The data given represent the main applications of the power tool. However, if the power tool is used for different applications, with different accessory tools, or is poorly maintained, the data can vary. This can significantly increase exposure over the total working period.

An accurate estimation of exposure should also take into account the times when the power tool is switched off, or when it is running but not actually being used for a job. This can significantly reduce exposure over the total working period.

Identify additional safety measures to protect the operator from the effects of noise and/or vibration, for example: maintaining the power tool and accessory tools, keeping the hands warm, organization of work patterns.

Noise values

| | |
|---|----------|
| Sound power level (L_{WA}) | 99 dB(A) |
| Uncertainty for the sound power level (K_{WA}) | 3 dB(A) |
| Emission sound pressure level (L_{pA}) | 88 dB(A) |
| Uncertainty for the sound pressure level (K_{pA}) | 3 dB(A) |

Vibration values

| | | TE 6-A36 | TE DRS-6-A |
|---|-----------------|-----------------------|-----------------------|
| Hammer drilling in concrete (a_h, HD) | B 36/5.2 | 16.8 m/s ² | 12.7 m/s ² |
| | B 36/9.0 | 16.2 m/s ² | 12.3 m/s ² |
| Vibration emission value, chiseling in concrete ($a_h, Cheq$) | B 36/5.2 | 8.1 m/s ² | •/• |
| | B 36/9.0 | 7.5 m/s ² | •/• |
| Uncertainty (K) | | 1.5 m/s ² | 1.5 m/s ² |

5 Operation

5.1 Preparations at the workplace

WARNING

Risk of injury by inadvertent starting!

- Before inserting the battery, make sure that the product is switched off.
- Remove the battery before making any adjustments to the power tool or before changing accessories.

Observe the safety instructions and warnings in this documentation and on the product.



5.2 Inserting the battery 2

⚠ CAUTION

Risk of injury! Inadvertent starting of the rotary hammer drill.

- ▶ Before installing the battery, check that the rotary hammer drill is switched off and that the forward/reverse switch is in the middle position (i.e. switch-on interlock engaged).

1. Push the battery into the battery holder until it engages with an audible click.
2. Check that the battery is seated securely.

5.3 Removing the battery 3

1. Press the release buttons on the battery.
2. Pull the battery out toward the rear.

5.4 Fitting the side handle 4

⚠ CAUTION

Risk of injury! Loss of control over the product.

- ▶ Check that the side handle is fitted correctly and tightened securely. Check that the clamping band is engaged in the groove in the product.

1. Release the side handle clamping band by turning the handle grip.
2. From the front, slide the depth gauge into the 2 guide holes.
3. Tighten the side handle clamping band by turning the handle grip.

5.5 Fitting and adjusting the depth gauge 5

- ▶ Fit the depth gauge, if necessary, and adjust it correctly.

5.6 Fitting / removing the chuck 6


⚠ CAUTION

Risk of injury! The depth gauge, if fitted but not used, might hinder the operator.

- ▶ Remove the depth gauge from the tool.

- ▶ Fit / remove the chuck.

5.7 Inserting accessory tool




1. Lightly grease the connection end of the accessory tool.
 - ▶ Use only genuine Hilti grease. Using the wrong grease can result in damage to the tool.
2. Push the accessory tool into the tool holder as far as it will go (until it engages).



3. After fitting the accessory tool, grip it and pull it in order to check that it is securely engaged.
 - The product is ready for use.

5.8 Removing the accessory tool



- Pull the chuck back as far as it will go and remove the accessory tool.

5.9 Overhead work 7

- Fit the DCD dust control ring for overhead work.

5.10 Chisel positioning 3

- Set the function switch to the \rightarrow position.

6 Types of work

6.1 Function selector switch 3

- Set the function selector switch to the desired working position.
 - Do not operate the function selector switch while the motor is running. **Risk of damage!**

6.2 Forward/reverse 3

- Set the forward/reverse switch to the desired direction of rotation.

6.3 Drilling without hammer action

- Set the function selector switch to the $\frac{1}{2}$ position.

6.4 Drilling with hammer action

- Set the function selector switch to the $\frac{1}{2}T$ position.

6.5 Chiseling

- Set the function switch to the T position.
 - For optimum motor cooling, select the forward direction, i.e. clockwise (direction of rotation for drilling).



7 Care and maintenance

7.1 Care and maintenance

WARNING

Risk of injury with battery inserted !

- Always remove the battery before carrying out care and maintenance tasks!

Care of the product

- Carefully remove stubborn dirt.
- Carefully clean the air vents, if present, with a dry, soft brush.
- Use only a slightly damp cloth to clean the housing. Do not use cleaning agents containing silicone as these can attack the plastic parts.
- Use a dry, clean cloth to clean the contacts of the product.

Care of the Li-ion batteries

- Never use a battery with clogged air vents. Clean the air vents carefully using a dry, soft brush.
- Avoid unnecessary exposure of the battery to dust and dirt. Never expose the battery to high levels of moisture (e.g. by being dipped in water or left in the rain).
If a battery has been soaked by moisture, treat it as a damaged battery. Isolate it in a non-flammable container and consult **Hilti** Service.
- Keep the battery free of extraneous oil and grease. Do not permit dust or dirt to accumulate unnecessarily on the battery. Clean the battery with a dry, soft brush or a clean, dry cloth. Do not use cleaning agents containing silicone as these can attack the plastic parts.
Do not touch the contacts of the battery and do not remove the factory-applied grease from the contacts.
- Use only a slightly damp cloth to clean the housing. Do not use cleaning agents containing silicone as these can attack the plastic parts.

Maintenance

- Check all visible parts and controls for signs of damage at regular intervals and make sure that they all function correctly.
- Do not use the product if signs of damage are found or if parts malfunction. Immediately have the product repaired by **Hilti** Service.
- After cleaning and maintenance, install all guards and protective devices and check that they are in full working order.



To help ensure safe and reliable operation, use only genuine Hilti spare parts and consumables. Spare parts, consumables and accessories approved by **Hilti** for use with your product can be found at your **Hilti Store** or online at: www.hilti.group

7.2 Cleaning the dust shield

- Clean the dust shield on the chuck with a dry, clean cloth at regular intervals.
- Clean the sealing lip by wiping it carefully and then grease it again lightly with **Hilti** grease.
- It is essential that the dust shield is replaced if the sealing lip is damaged.

8 Transport and storage

8.1 Transport and storage of cordless tools and batteries

Transport

CAUTION

Accidental starting during transport !

- Always transport your products with the batteries removed!
- Remove the battery/batteries.
- Never transport batteries loose and unprotected. During transport, batteries should be protected from excessive shock and vibration and isolated from any conductive materials or other batteries that may come in contact with the terminals and cause a short circuit. **Comply with the locally applicable regulations for transporting batteries.**



- ▶ Do not send batteries through the mail. Consult your shipper for instructions on how to ship undamaged batteries.
- ▶ Prior to each use and before and after prolonged transport, check the product and the batteries for damage.

Storage

WARNING

Accidental damage caused by defective or leaking batteries !

- ▶ Always store your products with the batteries removed!
- ▶ Store the product and the batteries in a cool and dry place. Comply with the temperature limits stated in the technical data.
- ▶ Do not store batteries on the charger. Always remove the battery from the charger when the charging operation has completed.
- ▶ Never leave batteries in direct sunlight, on sources of heat, or behind glass.
- ▶ Store the product and batteries where they cannot be accessed by children or unauthorized persons.
- ▶ Prior to each use and before and after prolonged storage, check the product and the batteries for damage.

9 Troubleshooting

If the trouble you are experiencing is not listed in this table or you are unable to remedy the problem by yourself, please contact **Hilti** Service.

9.1 The rotary hammer is not in working order

| Malfunction | Possible cause | Action to be taken |
|---|---|---|
| No response from the LEDs on the battery. | The battery is not fully inserted. | ▶ Push the battery in until it engages with a double click. |
| | Battery is discharged. | ▶ Change the battery and charge the empty battery. |
| | The battery is too hot or too cold. | ▶ Allow the battery to cool down or to warm up to room temperature. |
| 1 LED on the battery flashes. | Battery is discharged. | ▶ Change the battery and charge the empty battery. |
| | The battery is too hot or too cold. | ▶ Allow the battery to cool down or to warm up to room temperature. |
| 4 LEDs on the battery flash. | The rotary hammer has been over-loaded briefly. | ▶ Release the control switch and then press it again. |

9.2 The rotary hammer is in working order

| Trouble or fault | Possible cause | Action to be taken |
|---|--|--|
| No hammering action. | The rotary hammer is too cold. | ▶ Bring the tip of the drill bit into contact with the working surface, switch the rotary hammer on and allow it to run. If necessary, repeat the procedure until the hammering mechanism begins to operate. |
| | The function switch is set to "Drilling without hammering"  . | ▶ Set the function switch to "Hammer drilling"  . |
| The control switch can't be pressed, i.e. the switch is locked. | The forward / reverse switch is in the middle position. | ▶ Push the forward / reverse switch to the right or left. |



| Trouble or fault | Possible cause | Action to be taken |
|---|--|---|
| The drive spindle does not rotate. | The permissible operating temperature of the rotary hammer's electronics has been exceeded. | ▶ Allow the tool to cool down. |
| | Battery is discharged. | ▶ Change the battery and charge the empty battery. |
| | The function selector switch is not correctly engaged, is set to "Chiseling"  , or is set to "Chisel positioning"  . | ▶ Set the function selector switch to "Drilling without hammering"  or "Hammer drilling"  . |
| The rotary hammer switches itself off automatically. | The overload cut-out has been activated. | ▶ Release the control switch. Allow the rotary hammer to cool down. Press the control switch again. Reduce the load on the tool. |
| The battery runs down more quickly than usual. | Very low ambient temperature. | ▶ Allow the battery to warm up slowly to room temperature. |
| The battery does not engage with an audible "double click". | The retaining lugs on the battery are dirty. | ▶ Clean the retaining lugs and refit the battery. |
| The rotary hammer drill or the battery gets very hot. | Electrical fault | ▶ Switch off the rotary hammer drill immediately. Remove the battery and keep it under observation. Allow it to cool down. Contact Hilti service. |
| | The rotary hammer has been overloaded. | ▶ Use a more powerful tool. |
| The insert tool can't be released. | The chuck is not pulled back fully. | ▶ Pull the chuck back as far as it will go and remove the tool. |
| The tool makes no progress. | The rotary hammer has been set to reverse rotation. | ▶ Move the forward / reverse switch to the "Forward" position. |
| | The function switch is set to "Drilling without hammering"  . | ▶ Set the function switch to "Hammer drilling"  . |

10 Optional accessories

10.1 DCD dust control ring

The DCD dust control ring is an accessory for **Hilti** rotary hammer drills. It collects a high percentage of the dust produced by overhead work and it attaches quickly and easily to the rotary hammer drill.

10.2 TE DRS-6-A / TE DRS-6-A OSHA dust removal module

The TE DRS-6-A dust removal module is an accessory for the **Hilti** TE 6-A36 rotary hammer drill. It collects a high percentage of the dust and it attaches quickly and easily to the rotary hammer drill. The dust removal module has a built-in extractor fan. This fan is driven by its own motor. When the rotary hammer drill is switched on the dust removal module draws its electric power from the rotary hammer drill's battery.

The dust removal module is not suitable for working on metal and wood.

Conditions: TE DRS-6-A OSHA

The TE DRS-6-A OSHA satisfies the requirements of OSHA 1926.1153 Table 1. It has a filter-cleaning mechanism.

10.2.1 Fitting the dust removal module

 Before fitting the module, check that the attachment points and the electrical interfaces on the rotary hammer drill and dust removal module are free of dust and that the parts fit or move freely and easily.



1. Check the dust removal module for damage.
2. Check the ease of movement of the telescoping mechanism.
3. Set the forward / reverse switch on the rotary hammer drill to the middle position.
4. Remove the depth gauge from the side handle.
5. Position the dust removal module on the guides and from the front, push it on to the power tool until it engages.
6. After fitting, check that the dust removal module is secure.

10.2.2 Drilling with the dust removal module

1. Start the dust removal module by pressing the control button on the rotary hammer drill.
2. Hold down the control button until full suction power is reached.
3. Position the suction head with the edge seated flat against the work surface.
4. Drill the hole and ease the product slowly out of the drilled hole in order to catch as much dust as possible.

10.2.3 Emptying the dust box

 Regular cleaning and emptying are necessary because a full dust box or a clogged filter can lead to excessive dust formation.

Empty the dust box after drilling 8-10 holes (16 mm x 50 mm) (5/8 in x 2 in).

To minimize dust formation, carefully transfer the dust to a container with a tight-fitting lid.

1. Hold the power tool horizontal and allow it to run for a short time.
 - ▶ This ensures that residual dust deposits in the dust removal module are drawn into the dust box.
2. Press and hold down the release button of the dust box.
3. Pull the dust box down and clear of the dust removal module.
4. Empty the dust box.
 - ▶ Filter is clogged.
 - ▶ Change the filter.
 - ▶ Filter is free of dust.
5. Push the empty dust box back into the dust removal module from below until it engages.

10.2.4 Cleaning the TE-DRS OSHA filter

 Clean the filter after drilling 5 holes (16 mm x 50 mm) (1/2 in x 3 in).

- ▶ When suction power diminishes, slide the cleaning mechanism 5 times forward and back until it audibly clicks on each slide.

10.2.5 Removing the module

1. Move the forward / reverse switch on the rotary hammer to the middle position.
2. Press the DRS release button and hold it in this position.
3. Pull the dust removal module forwards away from the power tool.

11 Disposal

WARNING

Risk of injury due to incorrect disposal! Health hazards due to escaping gases or liquids.

- ▶ DO NOT send batteries through the mail!
- ▶ Cover the terminals with a non-conductive material (such as electrical tape) to prevent short circuiting.
- ▶ Dispose of your battery out of the reach of children.
- ▶ Dispose of the battery at your **Hilti Store**, or consult your local governmental garbage disposal or public health and safety resources for disposal instructions.

 Most of the materials from which **Hilti** products are manufactured can be recycled. The materials must be correctly separated before they can be recycled. In many countries, your old tools, machines or appliances can be returned to **Hilti** for recycling. Ask **Hilti Service** or your Hilti sales representative for further information.





-
- ▶ Do not dispose of power tools, electronic equipment or batteries as household waste!
-

12 RoHS (Restriction of Hazardous Substances)

Click on the link to go to the table of hazardous substances: qr.hilti.com/r4694033.
There is a link to the RoHS table, in the form of a QR code, at the end of this document.

13 Manufacturer's warranty

- ▶ Please contact your local **Hilti** representative if you have questions about the warranty conditions.



הוראות הפעלה מקוריות

1 מידע על הוראות הפעלה

1.1 על הוראות הפעלה אלו

- קרא את הוראות הפעלה האלה במלואן לפני השימוש המזרן. רק כך ניתן להבטיח עבודה בטוחה ונטולת תקלות.
- שים לב להוראות הבטיחות ולاذහרות שבהוראות הפעלה אלה וועל המוצר.
- שמרו את הוראות הפעלה תמיד בצדם למוצר, ואם אתה מעביר את המוצר לאדם אחר, צרף תמיד את הוראות הפעלה האלה.

1.2 הסבר הסימנים

1.2.1 אזהרת

האזהרות מחייבות מפני סכנות בשימוש במוצר. במודרך זה מופיעות מילוט המפתח הבאים:



סכנה !

מצינית סכנה מיידית, המוביל לפציעות גוף קשות או מוות.



אזהרה !

מצינית סכנה אפשרית, שיכלה להוביל לפצעות גוף קשות או מוות.



הירוחת !

מצינית מצב שעלול להיות מסוכן ולהוביל לפצעות גוף או לנקומים לרוכש.

1.2.2 סמלים בהוראות הפעלה

הסמלים הבאים מופיעים בהוראות הפעלה אלה:

| | |
|--|---|
| | שים לב להוראות הפעלה |
| | הנחיות לשימוש ומיעוט שימושי בסופר |
| | טיפול נכון בחומרים למייחזר |
| | אין להשליך לפסולת הביתיית מכשירים חשמליים וסוללות |
| | Hilti סוללה ליתיום-יון |
| | Hilti מטען |

1.2.3 סמלים באירועים

הסמלים הבאים משמשים באירועים:

| | |
|----------|--|
| 2 | מספרים אלה מפונים לאירוע המתחאים בתחילת הוראות הפעלה אלה. |
| 3 | המספרים באירועים מפונים לשלי עבודה החשובים או לכיבויים שחשובים לשלי העבודה. שלבי עבודה אלה או רכיביהם אלה מודגשים בטקסט במספרים מותאיים, לדוגמה (3). |
| (11) | מספר הפרטים מופיעים באירוע סקירה ונותאים את המספרים במקרה בפרק סקירת המוצר . |
| ! | סימן זה אמור לעורר את תשומת לך מיוחדת בעת השימוש במוצר. |

1.3 סמלים ספציפיים למוצר

1.3.1 סמלים על המוצר

הסמלים הבאים עשויים להופיע על המוצר:



2100247

עברית

15

| | |
|--|---|
| | קיור להלא הילימה |
| | קיור עם הילימה |
| | חציבה |
| | טיקום והזמל |
| | כוון הסיבוב |
| | מהירות סדק נקובה |
| | זרם ישיר |
| | ה מוצר תומך בתעכורה בתוכנים אלחוטית, המותאמת לשימוש עם פלטפורמות OS ו-Android. |
| | סדרת דגמי סוללות ליתיום-יון של Hilti ששימוש. שים לב לננתונים בפרק שימוש בהתאם לייעוד . |
| | סוללה ליתיום-יון |
| | עלולים אין להשתמש בסוללה כפתיש. |
| | אין להפעיל את הסוללה. אין להשתמש בסוללה שנחבה או שבזקתה באופן אחר. |

4.1 פרטיו המוצר

המוצרים של **Hilti** מיועדים למשתמש המ מקצועי, ורק אנשים מושרים, שעבורו הכשרה מותאמת, רשאים להפעיל, לתחזק ולתקן אוטום. אשיים אלה חייבים לאפונן מירוח את הסכנות האפשריות. המוצר המתויר ועובדים שלו עלולים להיות מסוכנים כאשר אבושים שלא עברו הכשרה מותאמת בהם באופן לא מקצועי או כאשר בעשו בהם שימוש שלא בהתאם לייעוד. שם הדגם והמספר הסידורי מוצאים על לוחית הדגם.

- רשום את המספר הסידורי בטבלה הבאה. בכל פניה לנציגינו או למעבדת שירות יש לציין את נתוני המוצר.

נתוני המוצר

| | |
|----------|--------------|
| ט' 6-A36 | פטיון |
| 04 | דוח: |
| | מספר סידורי: |

5.1 הצהרת תאימות

אנו מצהירים באחריותנו הבלעדית כי המוצר המתויר אכן תואם את התקנות והתקנים התקפיים. בסוף תייעוד זה ישנו צילום של הצהרת התאימות.

התיעוד הטכני שמור כאן:

Hilti Entwicklungsgesellschaft mbH | Zulassung Geräte | Hiltistraße 6 | 86916 Kaufering, DE

2.2 בטיחות

- 2.1 הוראות בטיחות כלליות לכל עבודה חשמליים**

اذhorא את כל הוראות בטיחות, ההנחיות, האירוטים והנתונים הטכניים המצורפים לכל העבודה החשמלי. אין ליצור תנחות עלול להוביל להתחשמול, לשורפה ו/או לפציעות קשות.

שמור את כל הוראות הבטיחות וההנחיות לעין בעתיד.

המונה "כל עבודה חשמלי" המשמש בהוראות הבטיחות מתייחס לכל עבודה חשמליים המוחברים לרשת החשמל (עם כבל חשמל) או לכל עבודה חשמליים הופעלים באמצעות סוללה נטענת (לא כבל חשמל).

בטיחות במקומם העבודה

 - שומר על אזור העבודה של נקי וודאג לתאורה מספקת.** חוסר סדר או תאורה לקויה במקומות העבודה עלולים לגרום לתאונות.
 - אין להפעיל את כל העבודה החשמלי בסביבה שקיים בה סכנת פיצוץ או שישנם בה נחלים, גדיים או אבק וליקים.**

כל עבודה חשמליים ייצורם ביצירות, עלולים להזכיר את האבק או האדים.



הרוק יולדים ואבשיטים אחרים מכל העבודה החשמלי במהלך השימוש בו. אם דעך תוסח אתה עלול לאבד את השילטה במכשיר.

ביטחוח בחשמל

תקע החשמל של כל העבודה החשמלי חייב להתאים לשיקע החשמל. אסור לשנות בשום אופן את תקע החשמל. אל תשתמש בשיקע מותאם ביחס עמו כל העבודה החשמלי הכוילים הגנת הארקה. שימוש בתកעים חשמליים שלא עברו שיבוי וشكען חשמל מותאים מפחית את הסיכון להתחשמלות. מכע מען הגוף בשטחים מותאים כגון צינורות, גוף חימום, תנורם ומקררים. קיימת סכנה בגבואה להתחשמלות כאשר הגוף שלך מוגרך.

הרוק כל עבודה חשמליים מגשם או רטיבות. חדרת מים לכל העבודה החשמלי מגדרה את הסיכון להתחשמלות. אל תשתמש בכל העבודה למטרות שלא לשם נועד, לדוגמה: אל תירט את כל העבודה החשמלי באמצעות הכבול ועל גופה לבוקת תתקע משיקע החשמלי בחושך, השתמש רק בכל מהות, שמן, פינות דוחה או חלקים בעים. כלים שנזקקו או שהסתובבו בחקלים אחרים מוגדרים את הסיכון להתחשמלות. כאשר אתה עבד עם כל העבודה החשמלי בחושך, השתמש רק בכל מאיריך המיעוד לשימוש חיצוני. שימוש בכל מאריך המאץ לשימוש חיצוני מפחית את הסיכון להתחשמלות. אם לא ניתן לימנע משימוש בכלי העבודה החשמלי בסביבה לחה, השתמש במסרר פחת. השימוש במסרר פחת מפחית את הסיכון להתחשמלות.

בטיחות של אבשיטים

היה ערב, שים לב למה שאתה עושה, וועל בתוכנה כאשר אתה עובד עם כל עבודה חשמלי. אל תעשייל כל עבודה חשמליים ששאתה עירף או תחת השפעת סמים, אלכוהול או תרופות. דברגע אחד של חסור תשומת-לב בדמן השימוש בכל העבודה החשמלי כדי לא לגרום פציעות קשות.

לבש תמיד מגן ומקפי מגן. לבש ציוד מגן אישי, כגון מסכת אבק, כגון מונעת החלקה, קסדה מגן או מגני שמיעה – בהחאים לסוג השימוש כלכלי – מקירה את הסיכון לפחות. עליל בטיוחות מונעות החלקה, קסדה מגן או מען הפעלה בשוגג. וזה שאל עבודה החשמלי בכדי לפחות ישבי שאתה מחור או לאספקת החשמל /או לפחות אתה מחור את הסוללה ולפבי הרמתה. אל תרכז את אכזר על המותג בדמן שאתה מושך או תחבור אותו לאספקת החשמל אשר הוא מפעעל, אחריה תלולות להיגדר האותות.

הרוק כל צווכן או מפתחות בריגים לפחות ישבי שאתה מפעעל את כל העבודה החשמלי. כל עבודה או מפתחות הנמצאים בקרבת חלקים מסתובבים עלילים לגרום פצעיות.

היכנע מתוחזקתו גוף לא בכוננות. עמוד באפונן יציב ושמור תמיד על שיוי משקל. כך תוכל לשלווט טוב יותר בכל העבודה החשמלי במצבים לא צפויים.

לבש בגדים מוחשיים. אל תלשב בגדים רתבים או תכשיטים. הרוק את השער, הבגדים וכפפות מחקלים עליים. בגדים רופפים, תכשיטים ושיער ארוך עלילם להיפפס בחקלים בעים.

כאשר יתuat להתקין התקין שיאית אבק לטליה יש לוואו שם מחוברים לחשמל, ויש להקפיד להשתמש בהם בצורה בכוננה. שימוש בהתקין שאית אבק מקטין את הסכנות הנבעות מהאבק.

אל תהיה שאנך בכוושאי בטיחות ואל תתעלם מהוראות בטיחות של כל עבודה חשמליים, גם אם שהשתמשה במכשיר פעומים רבת ואתא מכך אויטה. התנהלותו ושלניתו עלולה להוביל לפחות פצעיות קשות בתוך שבועות.

שימוש ויפוי בכל העבודה החשמלי

אל תעשייל כל עבודה מידי על המכשיר. השימוש בכל העבודה החשמלי המתאים לעבודה שאתה מבצע. כל העבודה החשמלי המתאים מבטיח לך עבודה טובה ובטוחה יותר בתחום ההספקה הנוקוב.

אל תשתמש בכל העבודה אם המהガ של איבן תקין. כל עבודה חשמלי שלא יתען עוד להפעיל או לכבות אותו מהווה סכנה ווש לתנקן.

נתק את תקע החשמל מהSKU ו/או הסר את הסוללה לפחות ישבי שאתה מבעץ צווכנים במכשיר, מחוליך כלים או לאחר שאתה מפסיק לעובוד עם המכשיר. אמצעי זהירות זה מונע הפעלה בשוגג של כל העבודה החשמלי.

שמור כל עבודה חשמליים שאיבם בשימוש הרוק מהישג ידם של ילדים. לפחות לאנשיים יודעים כיצד להשתמש בכל מכבשיך או שלא קרווא את ההוראות להשתמש במכשיך. כל עבודה חשמליים הם מוסכנים כאשר משתמשים בהם אנשים חסרי ניסיון.

טפל בכל עבודה חשמליים ובאכזרים בהקפדה. בזוק אם החקלים הנעים פעולים בצורה richtig וקיימים, אם ישם כלים שבירים או מקובלים היטיב, שהබחים חדים נתקעים פחות וקלים יותר להפעול. דאג לתיקון חקלים לא תקינים. תאותות רבות נגרמו עקב מהזדקקה לך של כל עבודה חשמליים.

שמור על כל החיתוך חדים וכקויים. כל חיתוך מטופלים היטיב, שהביבחים חדים נתקעים פחות וקלים יותר להפעול. השימוש בכל העבודה החשמלי, באכזרים, בכל העבודה הנוטפים וכן הלאה בהתאם להוואות אלה. ההחשה בתכאי העבודה וגפעולה שעליק לבצע. שימוש בכל העבודה החשמלי למטרות אחרות מלשלשן הוא מיעוד עלול להיות מסוכן.

שמור על דיזוט ואזרוי אחידה בקיים מכלון משwon ומגרטי. דיזוט ואזרוי אחידה חקלים אינם אפשררים לפעול בטוח ושליטה גבואה בכל העבודה החשמלי במצבים לא צפויים.

שימוש ויפוי בכל עבודה נתעכית

טען את הסוללות רק במטענים שהומלכו על ידי הייצור. טעינה של סוללה במטען המיעוד לטעינה של סוללות מסווג אחר עלולה לגרום לשרפפה.

השימוש בשם קר ורק בסוללות המתאימות לכל העבודה החשמלי. שימוש בסוללות אחרות עלול לגרום לשרפפה.



- שומר סוללות שאין בשימוש הרוחק מפהקדקי כייר משרדיים, מטבעות, מפותחות, מסומנים, בריגים או חפצים מתכתיים קשטים אחרים לשיכולים לגורם לשירות בין המגנים. קוצר בין מגע הסוללה עלול לגרום לכוויות או לשרפפה.
- שימוש שגוי עלל גורם לדיליפת נחלים מוסוללה. אל תיגע בNODES אלה. אם נגע בהם במקורה, שטופ את האזור במים. אם הנזול נוגע בעיניים, פנה לרופא. נחל סוללה שdalף עלול לגרום לגרויים בעור ולכוויות.
- אין להשתמש בסוללה ששונתה או שניזוקה. סוללות שניזקו או שנערכו בהן שניים עשויים עשויה לתגרה לא צפוי ולגורם לשליפה, לפיצוץ ולפצעות.
- אין לשחוף סוללות לאש או לטפרטורות גבוהות, אש או טפרטורות בגובהו -C 130° (265°F) עלולות לגרום לפיצוץ.
- צית לכל החבניות הבוגרות בהוותה לטעינה, וכך פעם אל תען את הסוללה או את הכל'ם הסוללה בסביבה שתמפרטורה בה נמצא מוחץ לעומת הפעילה. טעינה שגורה או טעינה בטempturaה שבסביבה מוחץ לעומת הפעילה בהוותה הפעילה עלולה להרים את הסוללה ולהגבר את הסיכון לשרפפה.

שירות

- דאג לתיקון כל העבודה החשמלי שלך ורק בידי טכנאים מוסמכים, המשמשים בחALKI חילוף מקורים בלבד. כך תבטיח שמייה על בטיחות העבודה במכשיר.
- אלتطפל בעצמך בסוללות שניזקו. רק היצן או מעבדה מורשית מטעמו רשאים לטפל בסוללות.

2.2 הוראות בטיחות לפטישות

- הנקיות בטיחות לכל העבודה החשמלי שמייה. עשו חזק עלול לפגוע בשמייה.
- השתמש במידות האחדה הנכונות המצוופות למכשיר. אובדן השיטה במכשיר עלול לגרום לפצעות.
- כאשר אתה מבצע עבודות שבון כל העבודה עלול לפגוע בקו חשמלי מוסתרים אחד במכשיר להתחשמלוות.
- הנקיות בטיחות לשימוש במתקדים ארכיטים.
- החל כל קידוח בסל"ד נוון, כשהמתקד מושב בחלק שבabajoה. קידוח בסל"ד גובה יותר עשוי לגרום למקודם להתקעם מעט כאשר הוא מושב בחלק שבabajoה. מוגע בחלק שבabajoה ולגורם לפצעות.
- דחף את המקדח ורק בכיוון האורכי ולא הפעלת לחץ מופת. המתקדים עשויים להתקעם ועקב כך להישבר או לגורם לאובדן שיטה ולפצעות.

2.3 הוראות בטיחות נוספת לפטישון

- בטיחות של אבכים
- השתמש במוטר ובאבכים רק בתנאי שהם נמצאים במצב טכני מושלם.
- אל תבצע בשום אופן شيئا'ם או נטיות בוחר או אבכים.
- השתמש במידות העדר המצוופות למוצר. אובדן שיטה של מוקם העבודה שלך. חומרים מעובדות הפיריה עשויים ליפול ולפצעו בעבודות פרויה יש לאבטוח את האזור בצד הנגיד של מוקם העבודה שלך. חומרים מעובדות הפיריה עשויים ליפול ולפצעו אנשים אחרים.
- אחוד את המוצר היבש תמיד בשתי ידיים בידות האחדה שלא. שמור על ידיות האחדה בקיות וbosht.
- כאשר אתה מבצע עבודות שהן האביר המחוור עלל לפגוע בקו חשמלי מוסתרים אחד במכשיר להתחשמלוות. המבוקד. מגע בקובים המוליכים דרום עלול להעירך דרום גם לחלקים מוסתרים במכשיר שלך ולגורם להתחשמלוות.
- אין לגעת בחALKIM מסתובבים – סכתנת פציעה!
- במהלך השימוש בוחרת בשח מכך עיניים, קסדת הגנה, מגני שמייה ומכסה כתימה מותאמת.
- לבש נעל בטיחות בעת החלפת כל. מגע בכל עלול לגרום לפצעות ולכוויות.
- השתמש במגיני עיניים. שביב חומר שוניים עוללים לפצע את הגוף והעיניים.
- אבק שונר במלול ליטוש, השחהה, חווון או קידוח עלל להקל כימיים מסוכנים. להלן כמה דוגמאות: עופרת או צבעים על בסיס עופרת; לבים, בסון וחומר קר' אחרים, אבן בעיטה ומוצריים אחרים המכילים סיליקט; עצים סטומטיים, כוונ אלון, בוק ועוז שuber טיפול כימי'; אבסטס או חומרים המכילים אבסטס. יש למודד את חשיפת המשתמש והאונשים בסביבה על פי דירוג הסכנה של החומרים הדורשים כדי לשלוט את השהפה ברמה בטוחה, לדוגמא.
- שימוש במיצקות שאיבת אבק או לבישת מסכת נשימה מהאייה. להלן רשימה של אמצעים כליים להפחחת החשיפה:
- נעזרה באזרז איזורר היבש.
- הימנענות מ מגע ממושך עם האבק.
- סיליק האבק מהפניהם והגוף.
- לבישת ביגוד מגן ושטיפות אוזניים חשופים בפנים ובסון.
- עורך הפקות התופעות ותרגילים לשיפור דרמת הדם לאצבעות. בעובדה מושחתת הרעדות החזקות מהמכשיר עשויות לגרום להפצעות בכלי הדם או במערכת העצבים של האצבעות, כפות הידיים או שורשי כף היד.
- בטיחות בחALKI
- לפני תחילת העבודה בזוק אם ישנים כבל CHALKI, צינורות גז או מים נסתרים. חALKIM מותכתים חיזוניים על הממכשיר עלולים לגרום האזור מפצעים או פיצוץ כאשר גז או מים. בזק כבב CHALKI, בזק גז או מים.
- טיפול ושימוש קפדיים בכבל CHALKI
- כבה את המוצר מיד אם הכל' נתקע. הממכשיר עשוי לסתות הצהה.



המטען עד לעצירה מלאה של המופוצר לפני שאתה מניח אותו.

2.4 הוראות בטיחות


- שים לב לכל הנחיות הבטיחות בתייעוד זה ועל המכשיר.
- השתמש בסוללה נשיימה המורחיקה מהפונים ומודרני הנשימה את האבק המשחרר בעת עבודות קידוח ותיקון.
- גם כאשר מזולג האבק מותקן יש להקפי ול השתמש בדית האחיזה הצידית של הפיטישון של **Hilti**.

2.5 טיפול ושימוש קפדיים בסוללות בטיחות

- צית לתקנות הנוגעות להובלה, אחסון והפעלה של סוללות בטענות מסווג ליתיום-יון.
- הרחיק את הסוללות ממקומות חמים מאוד, מקרינת שמש ישירה ומאס.
- אין לפוך, למלען, להטם למופטרו גבולה מ- 80°C (176°F) או לשחרר את הסוללות הנענות.
- אם הושתמש או לטען סוללה שקיבלו מכיה, שנפלו מגובה מוגבר או שניכזקו באופן אחר. בקרה כהה יש ליצור קשר עם השירות של **Hilti**.
- אם הסוללה מכיה כל כך שלא ניתן לגעת בה, יתכן שהיא אינה תקינה. הנה את הסוללה במקום לא דליק, גלי, רוחם מספיק וחומרים דליליים. אפשר לסתוללה להתקדר. אם בעור שעיה הסוללה עווין חמה מדי לגעה, אך היא פגומה. צור קשר עם השירות של **Hilti**.

3.1 תיאור

3.1.1 סקירת המופוצר



3.2 שימוש בהתאם ליעוד

המופוצר המותואר דהו פיטישון המופעל באמצעות סוללה. הוא מיועד לקידוח בפלדה, בעץ ובקירות לבנים, רקיזות בהלימה בבטון, ובקירות לבנים ולחדרה ולחזרו של ברגים. ניתן להשתמש במופער גם לעבודות חיבור קלות בקירות ולטיפול משלים בבטון.

- השתמש עבור מופער דה רך בסוללות ליתיום יון של **Hilti** מסדרת הדגמים .B 36.
- השתמש עבור עבור מזולג אבק **Hilti** C4/36 מהסדרה .C4/36

3.3 תוכנת סוללת הליתיום-יון

נוריות החיוו של סוללות הליתיום-יון מציגות את רמת הטעינה של סוללת הליתיום-יון וכן תקלות במכשיר. לאחר לחיצה על אחד ממשני לחצוי והשזרו של הסוללה תציג רמת הטעינה של סוללת הליתיום-יון.

| מספר | משמעות |
|------|--------------------|
| 4 | נוריות מהבהבות. |
| 3 | נוריות מהבהבות. |
| 2 | נוריות מהבהבות. |
| 1 | בורית אחת פאריה. |
| > | נוריות אחת מהבהבת. |



בדון שמתג הפעלה לחוץ וכן במשר 5 השניות הראשונות לאחר שחרור מתג הפעלה לא ניתן לבורר את רמת הטעינה של הסוללה. אם בורית החיווי של הסוללה מחבבובת, ראה בבקשה ההערות בפרק פתרון תקלות.



3.4 מפרט אספקה

פטישון, דית אחידה כידית, מעוזר عمוק, הוראות הפעלה.

www.hilti.group או בכתובת: **Hilti Store** מוצרים נוספתם המאושרם עבור המוצר שלך נמצא בפרק פתרון תקלות.

4 נתוני טכניים

4.1 סוללה

| | |
|-------------------------------|------------------|
| טמפרטורת הסוללה בתחילת הטעינה | 45 °C ... -10 °C |
| טמפרטורת אחסון | 40 °C ... -20 °C |
| טמפרטורת סביבה בעבודה | 60 °C ... -17 °C |
| מתוח עבודה עם סוללה נטענת | 36 וולט |

4.2 פטישון

| | |
|--|------------------|
| טווח קידוח בעץ (מקדח מלא) | 3 מ"מ ... 13 מ"מ |
| טווח קידוח בטון/קירות (קידוח בהלימה) | 3 מ"מ ... 20 מ"מ |
| טווח קידוח חומר בעיבוד (קידוח מלא) | 4 מ"מ ... 28 מ"מ |
| טווח קידוח הלימה בודדת בהתאם להליך EPTA מtarיך 05/2009 | 1,050 ג'ול |
| טווח קידוח הלימה בהתאם להליך EPTA מtarיך 01/2003 מתקובל בזיהוי | 3.7 ג'ג |
| טווח נקוב | 36 וולט |
| טווח קידוח חשמליים | 36 וולט |

4.3 ערכי רעש לפי EN 62841

ערכי לחץ הקול והרעידות המציגים בהוראות אלה נמדדו בהתאם לנוהל המדידה התקני, ונitinן להשתמש בהם לצורך השוואה בין כל שימושה חשמליים. הם מתאימים גם להערכת זמינותו של העומסים. הנתונים המציגים תקפים לשימושים העיקריים בכלי העבודה החשמלי. אולם אם משתמשים בכל העבודה החשמלי לשימושים אחרים, בשילוב בגדרים או ארים או אם המ鏗ר אינו עבר תחזוקה מספקת, הנתונים עשויים להיות גובוהה. בעקבות זאת פריסת העומס על מושך דון הפעולה ככל עשויה להיות גובוהה באופן משמעותי. לעומת זאת, הערכת מדדיות העומס יש לזכור כמה גורם גובוהה יכול להשפיע על ערכיו. בעקבות זאת פירמת העומס ממליצה על חישוב גובהו של מושך דון הפעולה כלו שבחם הוא אמן פועל אל תוך בשימוש בפעול. בעקבות זאת פירמת העומס ממליצה על חישוב גובהו כלו שיאפשר לרשות כנוכה באופן ממשמעות. יש לזכור בהיותו בטיחות ונוספות להגנה על המשתמש מפני ההשפעות של קול ו/או רuidות, כגון: תחזוקה של כלי העבודה החשמלי ושל כל העבודה המוחברים, שמירה על ידיים חממות, ארגון התהילתי העבודה.

ערכי רעש

| | |
|---|----------|
| א-וודאות ברמת הספק קול (K _{pA}) | 3 dB(A) |
| רמת לחץ קול (L _{pA}) | 88 dB(A) |
| רמת הספק קול (L _A) | 99 dB(A) |
| א-וודאות ברמת לחץ קול (K _{pA}) | 3 dB(A) |

ערכי ריעות

| TE DRS-6-A | TE 6-A36 | קייחות בהלימה בבטון (a _h , HD) | ערך ריעות בחציבה בבטון (a _{h, Cheq}) | אי-וודאות (K) |
|-------------------------|--------------------------|---|--|-------------------------|
| 2.2 מ'/שנ' ² | 12.7 מ'/שנ' ² | 16.8 מ'/שנ' ² | B 36/5.2 | (a _h , Cheq) |
| 2.2 מ'/שנ' ² | 12.3 מ'/שנ' ² | 16.2 מ'/שנ' ² | B 36/9.0 | |
| •/• | •/• | 8.1 מ'/שנ' ² | B 36/5.2 | (a _h , Cheq) |
| •/• | •/• | 7.5 מ'/שנ' ² | B 36/9.0 | |
| 2.2 מ'/שנ' ² | 1.5 מ'/שנ' ² | 1.5 מ'/שנ' ² | | |



5.1 הכנה לעבודה**אזהרה**

סכנת פציעה עקב התחלת תנועה בשוגן
לפני חיבור הסוללה ואשר מתחור כבוי.

- הסר את הסוללה לפני שאמה מבצע כוונוני כלשהם במכשיר או מחליפ אבידרים.

צ'ית להואות הבטיחות והاذירות שבתיעוד זה ולאלה הפזיניות על המוצר.

5.2 חיבור הסוללה 2**זהירות**

סכנת פציעה! תחילה עכורה בשוגג של הפטישון.

- לפני חיבור הסוללה ואשר הפטישון כבוי ושמагה כיון הסובב נמצא בעמדת האמצעית (חסימת הפעלה).

1. הכנס את הסוללה למחדיק במכשיר עד שהוא נגע לתצליל ברו.
2. ווא אשר הסוללה יושבת היטב.

5.3 הסרת הסוללה 3

1. לחץ על לחיצין השחרור של הסוללה.
2. משוך את הסוללה אחרת וחוץה.

4 התקנת ידיית האחידה הצדית**זהירות**

סכנת פציעה! אובדן השליטה במוצר.

- וכן כי ידיית האחידה הצדית מוקנת בכוונה ומהודקת היטב. ואשר חיבור הידוק נמצוא בחריץ המועד לו במוצר.

1. סובב את ידיית כדי לשחרר את המחדיק (חבק) של ידיית האחידה.
2. דחף את מעutor העומק מלפנים אל 2 חורי ההולכה הייעודיים.
3. סובב את ידיית כדי למתוח את המחדיק (חבק).

5.5 התקנה וכוכון של מעutor העומק 5

- התקן במרקם החוץ את מעutor העומק וכוכון אותו.


5.6 הסירה/התקנה של התפסונית 6**זהירות**

סכנת פציעה! מעטור עמוק מחומר ארך שאינו בשימוש עלול להפריע למשתמש.

- הסר את מעטור העומק מהמכשיר.


- הסר / התקן את התפסונית.





1. שמן קלוט את הקנה של הכליל.
- ◀ השתמש רק בגרדי מקורי של **Hilti**. גרייז לא מתאים עלול לגרום נזקים למיכניזם.
2. הכנס את קנה הכליל לתפסונית עד הסוף ואפשר לו להיבעל.
3. לאחר חיבור הכליל משווין אותו כדי לוודא שהוא בעל היבט.
- ◀ המוצר מוכן לעבודה.

5.8 הוצאה הכליל



- ◀ משווין את נעילת הכלילים לאחר עידוד הסוף וווזיא את הכליל.

5.9 עבודה מעל לראש 7

- ◀ התקן את טבעת איסוף האבק DCD לצורכי עבודה מעל לראש.

5.10 מיקום האדמל 8

- ◀ העבר את בורר הפעולות לעמדת זו .

6 עבודה

6.1 בורר פעולות 8

- ◀ העבר את בורר הפעולות למצב העבודה המבוקש.
- ◀ אין לתפעל את בורר הפעולות במהלך העבודה. סכנת מזק!

6.2 כיוון הסיבוב 9

- ◀ העבר את מותג כיוון הסיבוב לעמדת המתאימה עבור כיוון הסיבוב המבוקש.



6.3 קידוח ללא הלימה

- הבר את בורר הפעולות לעמدة זו ▶

6.4 קידוח בהלימה

- הבר את בורר הפעולות לעמدة זו ▶

6.5 ח齊בה

- הבר את בורר הפעולות לעמدة זו ▶

כדי להשיג קירור מיטבי של המכוון בחור סיבוב ימינה (כיוון הסיבוב בקידוח).

7 טיפול ותחזקה**7.1 טיפול ותחזקה****אזהרה!**

סכת פצעה כאשר הסוללה מחוברת!

לפנֵי ביצוע עבודות טיפול ותחזקה כלשון יש להקפיד להסר את הסוללה!
! ■

טיפול במוצר

- הסר בדירות לכלהן דבוק.

אם ישם, נקה את חורי האוזור בדירות בעדרת מברשת רכה ויבשה.

נקה את גוף המכשיר רק באמצעות מטלית לחה מעט. אל שימוש בחומר טיפול המכילים סיליקון, מאחר שהם עלולים

לפגוע בחALKי הפלסטיין.

נקה את המגנים באמצעות מטלית נקייה ויבשה.

טיפול בסוללות ליטיום-יון

עלול אין להשתמש בסוללה שחרצית האוזור של סולומים. נקה את חורי האוזור בדירות בעדרת מברשת רכה ויבשה.

מנע חשיפת הסוללה לאבק ולכלוך שלא לזרק. בשום אופן אין לשחוף את הסוללה לתוכה (לזגמה להטבל אותה

במים או להריכת אותה בgasן).

אם הסוללה נרטבה מאוד, יש להתייחס אליה כאול סוללה פגומה. בודד אותה במכיל לא זולק ונפה לשירות של Hilti.

שמור על הסוללה נקייה משמן וגרטי לא שיכים. אל תאפשר הצברות מוירחת של לכלהן ובקע על הסוללה. נקה את הוללה

במיטלית נקייה וכחה או במיטלית נקייה ויבשה. אל שימוש בחומר טיפול המכילים סיליקון, מאחר שהם עלולים

בחלקו הפלסטיין.

אל תיגע במגנים של הסוללה ואל תסיר מהגנים גרייז שהושם במפעול.

נקה את גוף המכשיר רק באמצעות מטלית לחה מעט. אל שימוש בחומר טיפול המכילים סיליקון, מאחר שהם עלולים

לפגוע בחALKי הפלסטיין.

תחזקה

בדוק באופן סדר את כל החלקים הגלויים כדי לאטור בדקים ולוזואו שכרכיבים פעולים באופן תקין.

אל תפעיל את המוצר אם ישם בדקים ו/או תקלות. פנה מיד לשירות של Hilti כדי לתיקן את המוצר.

לאחר עבודות טיפול ותחזקה יש להתחזק בחזרה את כל ציד הגנה ולבדק שהו פועל ב佗ונה תקינה.



לזכור הפעלה בטוחה של המכשיר יש להשתמש רק בחALKי חילוף וחומרים מתוכלים מקוריים. את חלקי החילוף, החומרים
המתוכלים והאבידרים שאושרו על-ידי Hilti עברו המוצר שlk'ת נמצא ב-Hilti Store שlk'ת נמצא ב-Hilti Store

7.2 ניקוי כיסוי ההגנה מפני אבק

נקה באופן סדר את כיסוי ההגנה מפני אבק בഫסונית באמצעות מטלית נקייה ויבשה.

נכיב בדירות את שפת האיטום ושמן אותה קלות באמצעות גרייז של Hilti.

אם שפת האיטום ניזוקה יש להחליף את כיסוי ההגנה מפני אבק ללא דיחוי.



8.1 הובלה ואחסון של כל עבודה בטענים וסוללות**הובלה****⚠ דANGER****התחלת פעולה בשוגג במהלך הובלה !****יש להובי את המכשיר כהסוללה מונתקת ממנה!****הובלה /ית.**

- הובלה אט סוללה/ית.
- עלולים אין להוביל את הסוללה בצרורה וחופשיות בין עוצמים לא אරודים. בדמן ההובלה הסוללות צרכיות להיות מוגנות מפני חבות ועידיות רבות וכן מבודדות מפני חומרים מוליכים כלשהם או סוללות אחרות, כדי שלא יוצר מגע בין מגעים של סוללות אחרות ונקב קר-קצה. **שים לב לילוי ההובלה בבדינתך בבעמך סוללות!**
- אסור לשולות סוללות בזואר. אם אתה רוצה לשולח סוללות לא פגומות, פנה לשם לך לחברת משלוחים והובלה.
- בדוק אם ישכם דקים ב;zואר ובסוללות לפני כל שימוש וכן לפני הובלה ארוכה.

אחסון**⚠ DANGER****דק לא מכון כהסוללה פגומות או זולפות !****יש לאחסן את המכשיר כהסוללה מונתקת ממנה!****אחסון**

- אחסן את המזמר ובסוללות במקום קריי ויבש. שים לב לערכי הגבול של הטמפרטורה, כמו גם בתנאים הטכניים.
- אין לאחסן סוללות על היפטוט. הקפד להוציא את הסוללה מהפטוטן בסיטם תחילת הפעינה.
- עלולים אין לאחסן סוללות בשימוש, על מקרחות חום או מאחווי דכויות.
- אחסן את המזמר ובסוללה הרחק מהישג ידם של ילדים או אנשים לא מושרים.
- בדוק אם ישכם דקים ב;zואר ובסוללות לפני כל שימוש וכן לפני אחסון ממושך.

9 תיקון תקלותאם מתרחשת תקלה שאינה מוסברת בטבלה זו או שאתה יכול לתקן בעצמך, פנה לשירות של **Hilti**.**9.1 הפטישון אינו מוכן לעבודה**

| תקלה | סיבה אפשרית | פתרונות |
|---------------------------------|-----------------------------------|--|
| הנוריות בסוללה אינם מציגות דבר. | הסוללה אינה מוכנת עד הסוף. | ואך שהסוללה ננעלת בצליל נקייה כפול. |
| הסוללה ריקה. | החלף סוללה, וטعن את הסוללה הריקה. | החלף סוללה, וטען את הסוללה הריקה. |
| נורית 1 מהבהבת בסוללה. | הסוללה חמפה מדי או קרה מדי. | אפשר לסתוללה להתקרר או האב את הסוללה לטמפרטורה החדר. |
| 4 נוריות מהבהבות בסוללה. | הסוללה ריקה. | החלף סוללה, וטען את הסוללה הריקה. |

9.2 הפטישון מוכן לעבודה

| תקלה | סיבה אפשרית | פתרונות |
|---|--|----------------------------------|
| אין הילימה. | הצמד את הפטישון לחומר ואפשר לו לעבוד בקצב טה. חזרו על הפעולה לפי הצורך עד שמערכת ההילימה מתחילה לעבוד. | הפטישון קר מדי. |
| בורר הפעולות נמצוא בעמדה "קידוח ללא הילימה"  . | העבר את בורר הפעולות לעמדה "קידוח בהילימה"  . | הפטישון קר מדי. |
| לא ניתן לחוץ על מותג הפעולה או שmag הפעולה חסום. | דחוף את מותג כיוון הסיבוב בעמדה האמצעית. יינונה. | מתוך כיוון הסיבוב בעמדה האמצעית. |



| תקלה | סיבה אפשרית | פתרונות |
|---|---|--|
| ציר המCKER שרים איננו מסתובב. | הטרכות האלקטרונית של הפטישון התחממה מעבר לטמפרטורת העבודה הפתורת. | אפשר למכשר להתקर. |
| הסוללה ריקה. | החלף סוללה, וטعن את הסוללה מחדש. | |
| בורר את בורר הפעולות לעמדת "קייזוח ללא הלימה" או "קייזוח בהלימה". | בורר הפעולות לא נתפס בעמדת או שעמדת נמצאת בעמדת "חציבה" או בעמדת "מייקום האידמל" - ^{ט-ט} . | החלף סוללה. |
| הפטישון נכבב אוטומטי. | פסיק ההגנה מפני עומס יתר קפז. | שחרר את מתג הפעולה. אפשר לפיסיון להתקר. לחץ שוב על מתג הפעולה. הפחת את העומס על המכשיר. |
| הסוללה מתרוקנת מהר מהרגיל. | טמפרטורת סביבה גבוהה מטוויה מודואן. | אפשר לשלול להתקופם בהדרגה לטמפרטורת החדר. |
| כפול ברו. | דיי הנעילה בסוללה מוליכים. | נקה את דיי הנעילה וחבר את הסוללה מחדש. |
| הפטישון או הסוללה מתחממים מואן. | תקלה חשמלית | כבה את הפטישון מייד. הסר את הסוללה והשכח עלייה. אפשר לה להתקר. צור קשר עם השירות של Hilti. |
| לא ניתן לשחרר את הכלים מהנעילה. | הפטישון לא נמשכה לאחר עד הסוף. | בחור מושך בעל הספק חזק. |
| הכלים אינם עושים את עבודותן. | הפטישון מכוון לסיבוב שטאללה. סיבוב ימינה. | מושך את מותג כיוון הסיבוב למצב הפטישון. |
| | בורר את בורר הפעולות לעמדת "קייזוח בהלימה" - ^{ט-ט} . | בורר את בורר הפעולות נמצאת בעמדת "קייזוח ללא הלימה" - ^{ט-ט} . |

10 אביזרים אופציונליים

10.1 בטעת איסוף אבק DCD

טבעת איסוף האבק DCD משמשת כאביזר עבור הפטישונים של Hilti. היא אוסף אחד גובה של האבק שנוצר בעבודות מעלה הראש, ואפשר להברא בקלות ובמהירות לפטישון.

10.2 מודול אבק TE DRS-6-A / TE DRS-6-A OSHA

מודול האבק TE DRS-6-A TE DRS-6-A36 TE של Hilti הוא אוסף אחד גובה של האבק שנוצר במהלך העבודה, והוא מתחבר בקלות ובמהירות לפטישון. במודול האבק ישנו מאורור ניוקה. הוא מונע באמצעות מנוע משולש. לאחר הפעלת הפטישון מקבל המודול את החשמל שלו מסוללה הפטישון. מודול האבק אינו מותאם לעבודות בעץ ובמתכת.

מארם: TE DRS-6-A OSHA

המcker TE DRS-6-A OSHA עומד בתנאי התקינה 1 OSHA 1926.1153 Table. הוא מצויד במנגנון לניקוי המסקן.

10.2.1 התקנת מודול האבק

לפני ההתקנה ודא שנקודות החיבור והמסנחים החשמליים בפטישון ובמודול האבק נקיים מאבק ובאים בצוורה חלקה.



1. בדוק אם ישם נקדים מודול האבק.
2. בדוק שהטולקופ נב冤 בצוורה חלקה.
3. העבר את מותג כיוון הסיבוב של הפטישון לעמדת האמצעית.
4. נתק את מעדר העומק מידית האחידה הצידית.
5. דחף את מודול האבק מקימה לע המכנים, עד שהוא נגען.
6. בדוק לאחר ההתקנה שמודול האבק נועל היטב.



10.2.2 קידוח עם מודול האבק

1. כדי להפעיל את מודול האבק לחץ על כפתור הפעלה של הפטישון.
2. החזק את כפתור הפעלה לחוץ עד להגעה להספק השאייבת המורבי.
3. הצד את ראש השאייבת בדוחה ישרה לחומר שבזבודה.
4. קדח את החור ומשוך את המוצר באטיות אל מחוץ לקדרה, כדי לקלוט מה שיזור האבק.

10.2.3 ריקון מכל האבק 11

כאשר מכל האבק מלא או המטען סתום תיתכן התפתחות גזולה של האבק, לפיכך יש לרוקן את מכל האבק באופן סדרי.
רוקן את מכל האבק לאחר 8–10 קידוחים (16 מ"מ × 50 מ"מ) או (5 אינץ' × 2 אינץ').
כדי למנוע את התפתחות האבק, שמור את האבק במכל סגור.

1. החזק את המכשיר מאהן והפעיל אותו לדמן קצר.
- ◀ קר שאריות האבק שנותרו במודול האבק ישאבו מכל האבק.
2. לחץ על לחץ השחרור של מכל האבק והחזק אותו לחוץ.
3. משוך את מכל האבק למיטה אל מחוץ למודול האבק.
4. רוקן את מכל האבק.
- ◀ המטען מ脱落ן.
5. דחף את מכל האבק הריק מלמטה לתוך מודול האבק, עד שהוא נתפס.

10.2.4 ניקוי מסנן TE-DRS-OSHA 13

נקה את המטען לאחר 5 קידוחים (16 מ"מ × 50 מ"מ) או (5 אינץ' × 3 אינץ').

- ◀ כאשר הספק השאייבת פוחת דחף את מגנון הניקוי 5 פעמים קדימה ו-5 פעמים אחורה, בכל פעם עד שאתה שומע "קליק".

10.2.5 הסרת מודול האבק 12

1. העבר את מתג כיוון הסיבוב של הפטישון לעמדת האמצעית.
2. לחץ על לחץ השחרור ה-DRS והחזק אותו לחוץ.
3. משוך את מודול האבק קדימה והסר אותו מהמכשיר.

11 סילוק

סכנת פציעה בעקבות סילוק לא תקין סכנה בריאותית מהשתחררות גדים ונחלים.

- ◀ אין לשולח סוללות פגומות!
- ◀ כסא את החיבורים באמצעות חומר לא מוליך, כדי למנוע קצר.
- ◀ סלק סוללות קר שהן לא יכול להגע לידיהם של ילדים.
- ◀ סלק את הסוללה ב- **Hilti Store** או פנה לחברת הפיתוח האחראית.



ה מוצרים של **Hilti** מיוצרים בחALKם הגדול מחומרים ניטניים למיחזור. כדי שניתן יהיה למוחזרים פרודת חומרים מקצועית. במדינות רבות **Hilti** מקבל את המכשירי הישן של בחזרה לצורכי למיחזור. פנה לשירות של **Hilti** או למשוק.

◀ אין להשליך כל עבודה חשמליים, כלים אלקטרוניים וסוללות לפסולת הביوتית!

12 RoHS (תקינה להגבלת השימוש בחומרים מסוכנים)

בקישור הבא תמצוא את טבלת החומרים המסוכנים: qr.hilti.com/r4694033.
קישור לטבלת RoHS נמצא בסוף תייעוד זה, בצדות קוד QR.

13 אחוריות יצורן

◀ אם יש לך שאלות בנוגע לנושא תאבי האחריות, אבא פנה למשוק **Hilti** הקרוב אליו.



EC Declaration of Conformity | UK Declaration of Conformity



Manufacturer:
Hilti Corporation
Feldkircherstraße 100
9494 Schaan | Liechtenstein

UK Importer:
Hilti (Gt. Britain) Limited
No. 1 Circle Square, 3 Symphony Park
Manchester, England, M1 7FS

TE 6-A36 (04) | TE DRS-6-A (02)

Serial Numbers: 1-9999999999

| | | |
|---|--------------------------|--------------------------------|
| 2006/42/EC Supply of Machinery (Safety) Regulations 2008 | EN 62841-1:2015, AC:2015 | EN IEC 62841-2-6:2020/A11:2020 |
| 2014/30/EU Electromagnetic Compatibility Regulations 2016 | EN IEC 55014-1:2021 | EN IEC 55014-2:2021 |
| 2011/65/EU The Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012 | | |


Dr. Tahar Zrilli
Head of Quality and Process Management
Business Area Electric Tools & Accessories

Schaan, 22.02.2023


Edward-Louis Przybylowicz
Head of BU Power Tool & Accessories
Business Area Electric Tools & Accessories



<http://qr.hilti.com/r4694033>



Hilti Corporation
LI-9494 Schaan
Tel.: +423 234 21 11
Fax: +423 234 29 65
www.hilti.group



2100247